

Printed by EAST

UserID: TThomas1

Computer: WS06537

Date: 03/23/2002

Time: 21:53

	Type	L #	Hits	Search Text
1	BRS	L2	28456 8	capacitor
2	BRS	L3	1811	trench\$2 near3 2
3	BRS	L4	5263	trench\$2 near3 (isolation or oxide or insulation)
4	BRS	L5	318	3 and 4
5	BRS	L7	3044	shallow adj trench adj isolation
6	BRS	L8	7476	BPSG
7	BRS	L9	6171	PSC
8	BRS	L10	8674	TEOS
9	BRS	L11	256	7 same (8 or 9 or 10)
10	BRS	L12	4	7 same 8 same 9 same 10
11	BRS	L13	4	7 and (8 near 9 near 10)
12	BRS	L14	5247	trench near isolation
13	BRS	L15	4	14 and (8 near 9 near 10)
14	BRS	L16	4	trench same (8 near 9 near 10)

	DBs	Tim Stamp	Comment s	Error Definition	Err ors
1	EPO; JPO; DERWENT	2002/03/23 17:09			0
2	EPO; JPO; DERWENT	2002/03/23 17:10			0
3	EPO; JPO; DERWENT	2002/03/23 17:11			0
4	EPO; JPO; DERWENT	2002/03/23 17:11			0
5	USPAT; US-PGPUB	2002/03/23 19:53			0
6	USPAT; US-PGPUB	2002/03/23 19:59			0
7	USPAT; US-PGPUB	2002/03/23 19:59			0
8	USPAT; US-PGPUB	2002/03/23 20:00			0
9	USPAT; US-PGPUB	2002/03/23 19:56			0
10	USPAT; US-PGPUB	2002/03/23 19:56			0
11	USPAT; US-PGPUB	2002/03/23 19:57			0
12	USPAT; US-PGPUB	2002/03/23 19:58			0
13	USPAT; US-PGPUB	2002/03/23 19:58			0
14	USPAT; US-PGPUB	2002/03/23 19:58			0

	Typ	L #	Hits	Search T xt
15	BRS	L17	2583	trench near isolation
16	BRS	L18	2319	BPSG
17	BRS	L19	4288	PSG
18	BRS	L20	1769	TEOS
19	BRS	L21	0	17 and 18 and 19 and 20
20	BRS	L22	4047	trench near4 fill\$3
21	BRS	L23	1	22 and 18 and 19 and 20

	DBs	Time Stamp	Comm nt s	Error Definition	Err ors
15	EPO; JPO; DERWENT	2002/03/23 19:59			0
16	EPO; JPO; DERWENT	2002/03/23 19:59			0
17	EPO; JPO; DERWENT	2002/03/23 19:59			0
18	EPO; JPO; DERWENT	2002/03/23 20:00			0
19	EPO; JPO; DERWENT	2002/03/23 20:01			0
20	EPO; JPO; DERWENT	2002/03/23 20:01			0
21	EPO; JPO; DERWENT	2002/03/23 20:02			0